

EAST (MAMMOGRAPHY)

KEY NOTES

- 3. MOUNT A5145, HOOK, AT 1372 [4'-6"] AFF. PROVIDE 2-A5145'S FOR NAVY PROJECTS ONLY.
 MOUNT 1-A5145 AT 1372 [4'-6"] AFF AND 1-A5145 AT 1524 [5'-0"] AFF.

 4. P3200, UITR ELECTRONIC LAVATORY, MAY BE USED INSTEAD OF P3100, LAVATORY. FOR THE P3200 PROVIDE EITHER BATTERY POWER OR HARD WIRED CONNECTION.

General Notes:

- For typical equipment mounting heights see "TYPICAL EQUIPMENT MOUNTING HEIGHTS" drawing.
- 2. MIL—STD—1691 data can only be accessed from the Equipment Plan.

XRAY DIAGNOSTIC, MAMMOGRAPHY (XDMO1)

0 1000 2000 RADIOLOGY/NUCLEAR MEDICINE ELEVATIONS 11.15 NSM (120 NSF) DATE: 07/12/2001 1:50 SCALE (MILLIMETERS)